Gabriel Metals, LLC
Parts Consigned to Repair Shops

Date 18-Mar-17
Location ATS
Name Jay Cordero, President
Email cordero@atshouston.com
Address 15653 N. Brentwood, Channelview, TX. 77530
Phone 281-452-2441 (O), 832-283-6259 (M)

Model / Manuf.	Part Number	Part Description	Condition	Qty	Comment
W501B-B6	1233E83G03	Combustion Baskets	Service Run	14	Repairable
W501AA-D4	1857J46G01	Row 2 Blades	Service Run	88	Repairable
W501AA-D4	1721D88004	Row 2 Blades	Service Run	2	Repairable
W501B-D4	231T321001	Row 3 Vanes	Service Run	16 (1 set)	Repairable
W501AA-D	2012H0001	Row 4 Blades	Service Run	51	Repairable
W501B3-B6	2358P4001	Transition pieces	Service Run	4	Repairable
W501 F	2246J2G01	Row 1 segments	Service Run	32 (1 set)	Repairable
GE7FA	323E1913G001	Combustion liners	Service Run	28	Repairable
W501D6	792J500-001	Row 1 Vane segments	Service Run	72	Repairable
W501D6	795B2001	Row 1 Vane segments	Service Run	48 (1 set)	Repairable
W501D6	1236E09001	Row 3 Vane segments	Service Run	14	Repairable
W501D6	1867J88G01	Row 1 Turbine Blades	Service Run	74	Repairable
W501D6	1312E70001-2	Row 2 Turbine Blades	Service Run	63	Repairable
W501D6	1280E02G01	Row 3 Turbine Blades	Service Run	50	Repairable
W501D6	1278E98G01	Row 4 Turbine Blades	Service Run	48	Repairable
W501F	775J618001-06	Row 2 Turbine Blades	Service Run	26	Repairable
W501F	775JB18001-04	Row 2 Turbine Blades	Service Run	38	Repairable
W501F	775JB1801-5	Row 2 Turbine Blades	Service Run	5	Repairable
W501F	2074J05SUB006	Row 3 Turbine Blades	Service Run	104	Repairable
W501F	2074J98-001SUB4	Row 1 Segments	Service Run	43	Repairable
W501F	2074J98-001SUB2	Row 1 Segments	Service Run	48	Repairable
W501F	2245J93-001SUB2	Row 2 Segments	Service Run	42	Repairable
W501F	6522700REVA	Row 2 Segments	Service Run	41	Repairable