

**Gabriel Metals, LLC**  
**Parts Consigned to Repair Shops**

**Date** 14-Jan-16  
**Location** Genex  
**Name** Brandon Hall, President  
**Email** [bhall@genexturbine.com](mailto:bhall@genexturbine.com)  
**Address** 68 Prospect Hill Rd. East Windsor, CT. 06088  
**Phone** 860-288-2401

| Model /<br>Manuf. | Part Number  | Part Description   | Condition  | Qty          | Comment                   |
|-------------------|--------------|--------------------|------------|--------------|---------------------------|
| W501D5            | 7863D44-xxx  | Combustion Basket  | Repairable | 14(1<br>set) | In Genex repair procedure |
| W501F             | 1269J37      | Row 2 Vane Segment | Repairable | 24(1<br>set) | In Genex repair procedure |
| W501F             | 1269J37      | Row 2 Vane Segment | Repairable | 24(1<br>set) | In Genex repair procedure |
| GE 7FA            | 114E5657G016 | End cover          | Repairable | 14-1<br>set  | closed                    |
| GE 7FA            | 114E5657G016 | End cover          | Repairable | 14-1<br>set  | In repair procedure       |
| GE 7FA            | 114E5657G016 | End cover          | Repairable | 14-1<br>set  | in repair procedure       |
| GE 7FA            | 114E5657G016 | End cover          | Repairable | 14-1<br>set  | in repair procedure       |
| GE 7FA            | 114E5657G016 | End cover          | Repairable | 14-1<br>set  | in repair procedure       |