

Gabriel Metals, LLC
Parts Consigned to Sales Agency Affiliate

Date 18-Mar-17

Location Global IGT Solutions

Name Marcial Trujillo, President Fernando Nieves, Sales

Email mtrujillo@globaligt.com, fnieves@globaligt.com

Address 817 S. Mill St. Suite C109, Lewisville TX. 75057

Phone 972-977-6211,

Model / Manuf.	Part Number	Part Description	Condition	Qty	Comment
GE 7FA		Transition Pieces	Repairable	14 (1 set)	Complete visual inspection
GE 7FA		Combustion Liners	Repairable	14 (1 set)	Complete visual inspection
GE 7FA		Stage 2 Shroud Blocks	Repairable	48 (1 set)	Complete visual inspection
GE 7FA		Stage 1 Inner Support Ring	Repairable	1	Complete visual inspection
GE 7FA	TBD	Row 3 Shroud Blocks	Repairable	36 (1 set)	Complete visual inspection
GE 7FA	109E9918P1	Row 1 Buckets	Repairable	91	Complete visual inspection
GE 7FA	116E1553P001	Row 3 Buckets	Repairable	92 (1 set)	Complete visual inspection