

Gabriel Metals, LLC
Parts Consigned to Repair Shops

Date 18-Mar-16
Location Turbine Resources
Name Bill McCall, President
Email triwm@sbcglobal.net
Address 1005 Stanley Dr., Euless, TX. 76040
Phone 940-453-6804 (M) or 817-540-1041

Model / Manuf.	Part Number	Part Description	Condition	Qty	Comment
W501 D5		Row 1 ring segments	Repairable	48-1 set	weld repair complete
W501 D5		Row 2 ring segments	Repairable	48-1 set	incoming
W501 D5		Row 3 ring segments	Repairable	28	incoming
W501 D5	1723D1001	Clam shells	Repairable	42	In Turbine Resource repair procedure
W501 D5	7898D70001	Row 1 blades	Repairable	80-1 short of a set	In Turbine Resource repair procedure
W501 D5A		Row 2 vanes	Repairable	16-1 set	READY FOR SALE
W501D5 A		Seals	Repairable	27	In Turbine Resource repair procedure
W501D5 A		Transitions	Repairable	20	incoming
W501D5 A		BullHorn	Repairable	14	incoming
W501D5 A		Baskets	Repairable	41	
W501 F		Row 2 Vane Segments	Repairable	16	incoming
W501 F	2284J85-001	Row 3 Vane Segments	Repairable	16	incoming