# Gabriel Metals, LLC
## Parts Consigned to Repair Shops

**Date** 23-Mar-16
**Location** Trinity Turbine Technology
**Name** David Smith, david.smith@trinityturbine.com & Kevin Martinez, kevin.martinez@trinityturbine.com
**Address** 7650 A North Country Rd. 48 Iowa Colony, TX. 77583
**Phone** 281-431-6691 (O) 210-857-1360 (M)

| Model / Manuf. | Part Number | Part Description | Condition | Qty | Comment |
|---|---|---|---|---|---|
| GE Frame 7FA E | 109E9111P002 | Stage 1 Nozzle | Repairable | 24 | In repair process |
| GE Frame 7FA E | 103E3241 | Stage 2 Nozzle | Repairable | 24 | In repair process |
| GE Frame 7FA E | 114E5697G002 | Transition | Repairable | 14 | In repair process |
| GE Frame 7FA E | 586E1129G001 | End Caps | Repairable | 14 | In repair process |
| GE Frame 7FA E | 119E6643G007,8,9 | Combustion Liners | Repairable | 14 | In repair process |
| GE Frame 7FA E | 115E6176P1 | Stage 2 Shroud Blocks | Repairable | 48 | In repair process |
| GE Frame 7FA E | 112E1028P1,P2,P3 | Stage 3 Shroud Blocks | Repairable | 36 | In repair process |
| GE Frame 7FA E | 115E6176P1,P2 | Stage 2 Shroud Blocks | Repairable | 48 | In repair process |
| W501DF42 | 7863D44G04 | Combuster Basket | Repairable | 12 | In repair process |
| W501DF42 | 7863D44G04 | Combuster Basket | Repairable | 14 | In repair process |